SAFETY INSPECTION REPORT IN FAVOUR OF:

Name of Inspecting Engineer with Contact No. and e-mail:

Name of Building:	nil hoenka pasac serval	
Name of the Owner/Applicant:		
Address/Location of the Structure:	Railway Approach road Harray A	ra
Contact No. of Owner/Applicant and mail id:	7889652001	
Year of Construction:	2018-19	
Building Use with Name of Prominent Users:	Schooling purpose	
Purpose of issuance of Certificate:	sayety certificate	

VISUAL INSPECTION:

General Observations:

S.No	DESCRIPTION	REMARKS				
1.	Type of Building	Framed Structure				
2.	Age of Building	Five years (05)				
i)	As per Building Permission					
ii)	As per Electric Connection/Water Connection					
iii)	As per Affidavit by the Applicant.					
iv)	As per Physical Assessment by Inspecting Officer					
3.	No of wings					
4.	Mode of Use	School				
5.	No. of Stories	04 (four)				
6.	Architectural Plan Name of the Architect					
7.	Structural Plan Name of the Consultant	Buildren Derign & construction By behave. Buildren Derign & commettin By behave.				
8.	Building Plan Approval Date					
9.	Occupation Certificate Date	-				
10.	Last Repair Date					
11.	Details of Repair.					

^{*} Age Proof supported by documents 2(i) or 2(ii) or 2(iii).

Signature of Inspecting
Junior Engineer

CHAIRMAN G.D.GOENKA PUBLIC SCHOOL Assistant Executive Engineer

Structural Observations:

S.No	DESCRIPTION	LOCATION OF COMPONENT	GRADE	REMARKS
	FOUNDATION			
	Foundation Settlement/Timber Rot	lin		
	Floor Settlement	M		
	Foundation exposed to aggressive environment like water logging/dampness etc.	"		
A	SETTLEMENT/TILT DEFROMATION			•
1.	Column	Nil		
2.	Walls	wil		
В	CRACKS			
1.	Column	Nil		
2.	Beams	"		
3.	Slab	"		
4.	Plaster	1/		
5.	External wall	"		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
6.	Internal wall	11		
С	CORROSION OF STEEL	7		
1.	Column	Nil		
2.	Beam	"		
3.	Slab	"		
D	LEAKAGES AND DAMPNESS AND WATER PROOFING			
1.	External wall	Nil		
2.	Toilet	"		
3.	Terrace	"		
4.	Top floor slab	()		
5.	Inspection of overhead water tank	"		
6.	Inspection of underground water tank	"		
7.	Leakages & damages plumbing lines/waterlines, drainage lines	"		

Signature of Inspecting
Junior Engineer

CHAIRMAN SCHOOL

Signature of Inspecting
Assistant Executive Engineer

	FIRE SAFETY						
	Fire gap on each side i.e. North, South, East and West.	To be reported by Concerned Fire and Emergency Ser	ted by Concerned Fire and Emergency Services				
	Number of Exits	Department Department					
	Sufficient width of Stair Case for safe exit of inhabitants						
	Provision of ramps (if any)						
	Status of Heavy Suspended Fixtures						
	Such as Heavy false Ceilings etc.						
E	DEFLECTION						
1.	Beam .	Nû					
2.	Slab	11					
3.	Overloading on slab	11					
4.	Cantilever deflection	1,					
F	CONDITION OF OTHER COMPONENTS						
1	Staircase	Croud					
2.	Balcony	· · ·					
3.	Flooring	"					
4.	Ducts	11					
5.	Terrace	1)					
6.	Plumbing System	"					
7.	Electric Supply Line	11	· ·				
8.	Water Supply Line	1,					

^{*} The report regarding defects to be duly supported by photographs which shall also include photographs of structure from all four sides.

Payment of Rs 2000/- has been received vide G.R. No. 2365893 Dated: 04/05/2024

Comments/Nota	visual	inspe	clin, the	exmeline	is	in			lin
On me	contigio	- 1	is valid	only is		norl	weath	er c	undiltin
and is	valid	lex	only o	ne syca	· .				
37		8	1						

Signature of Inspecting
Junior Engineer

CHAIRMAN SCHOOL

Signature of Inspecting
Assistant Executive Engineeringer
Assistant Executive Engineeringer

OFFICE OF THE EXECUTIVE ENGINEER PWD(R&B) DIVISION KHANABAL

	n and in light of recorded above at S.No,
,,, the struct	ure is Sound/ Exhibits Rectifiable Defects/Non-Rectifiable Defects
with Major Distress.	
The Corrective Action in respect of rectifiable	e Defects if required above are anticipated to be completed by
	CERTIFICATE
The Structure in the opinion of the undersigned	is hence assessed Safe/Unsafe for intended functional use based on
Detailed Safety Inspection Report subject to requi	red Corrective actions in case of identified rectifiable Defects.
	late of occurrence of a natural disaster or an act of Major structural
	ate of completion of identified Corrective Actions if not completed,
whichever is earlier.	
Note:	
This safety inspection report is based on abso	olute visual inspection of the structure, the information and explanations as
	the best of the knowledge and belief of the inspecting officers and shall not
	Structural Inspection. The R&B Department shall not be responsible for any
	ement/ negligent maintenance/ overloading and misuse of the structure and
all such eventualities/Occurrences.	9 500 Pa
NI A	\circ
March	Show -
Signature of Inspecting	Signature of Inspecting Assistant Executive Engineer
Junior Engineer	RAS Sub-Division Charles to the Control of the Cont
Sign	ature of theer
Execut	ive Engineer utog
/ /	
8	•
I acknowledge receipt of this report.	No: 970 Dt: 04 / 05 /2024
M c.	10000000000000000000000000000000000000
Megano M	
B) July J	
Signature of Owner / applicant	
Date: 04/05/2024	Φ.
Date: 6970572024 Contact No: +91 <u>9469/83056</u>	
Mail Id:	M real
71dii 10	CHAIRMAN SCHOOL
	COENKA PLIBLIC SOLL
	G.D.GOLL